



Bothenhampton & Walditch  
Parish Council since 1886

Mr M Hallam  
PlayQuest

Via email

8<sup>th</sup> February 2021

Dear Mr Hallam

RE: LOWER WALDITCH PLAY AREA

A recent inspection of the play area you installed at the Lower Walditch Play Area, Gundry Lane, Bridport, last summer has highlighted an absence of proper marking on the equipment as required in BS EN 1176. The inspections were carried out by Ken Hussey, an inspector you have approved.

Please would you supply a fixing / plate for each of the five items of equipment you have installed for us showing:

- manufacturer name
- year of manufacture
- equipment reference number and date of BS EN 1176

The plates can then be fixed to the equipment so that the installation conforms to BS EN 1176.

Also absent is the 'basic level mark' which would show us the level to which the surfacing should be maintained. Some of the posts are mounted on metal supports, but on one side of the play area they are buried in the surface (grass). Please would you advise how this mark can be added to the equipment.

We look forward to your response.

Yours sincerely

A J Basker  
Chairman  
Bothenhampton & Walditch Parish Council  
[clerk@bothenhamptonwalditchparishcouncil.com](mailto:clerk@bothenhamptonwalditchparishcouncil.com)  
Website [www.bothenhamptonwalditchparishcouncil.com](http://www.bothenhamptonwalditchparishcouncil.com)